

Dew Point Chart							
Dew Point		Gram/Nm3	Ppm/Vol	Dew Point		Gram/Nm3	Ppm/Vol
Minus	100	0.0000111	0.0138	Zero	0	4.84	6020
Minus	90	0.0000767	0.0953	Plus	1	5.21	6480
Minus	80	0.000434	0.54	Plus	2	5.59	6953
Minus	70	0.00207	2.57	Plus	3	6.02	7487
Minus	60	0.00857	10.7	Plus	4	6.45	8022
Minus	55	0.0166	20.6	Plus	5	6.91	8595
Minus	50	0.0317	39.4	Plus	6	7.41	9216
Minus	48	0.0399	49.6	Plus	7	7.94	9875
Minus	46	0.0507	63	Plus	8	8.51	10584
Minus	44	0.0642	80.1	Plus	9	9.1	11318
Minus	42	0.0816	101.5	Plus	10	9.74	12114
Minus	40	0.102	126.9	Plus	11	10.4	12935
Minus	38	0.127	158	Plus	12	11.1	13806
Minus	36	0.159	197.8	Plus	13	11.9	14800
Minus	34	0.197	245	Plus	14	12.7	15796
Minus	32	0.244	303	Plus	15	13.5	16791
Minus	30	0.301	374	Plus	16	14.4	17885
Minus	28	0.371	461	Plus	17	15.4	19030
Minus	26	0.454	564	Plus	18	16.4	20396
Minus	24	0.554	689	Plus	19	17.4	21641
Minus	22	0.675	840	Plus	20	18.5	23020
Minus	20	0.816	1015	Plus	21	19.7	24502
Minus	19	0.899	1118	Plus	22	21	26120
Minus	18	0.0989	1231	Plus	23	22.3	27736
Minus	17	1.09	1356	Plus	24	23.7	29477
Minus	16	1.19	1480	Plus	25	25.1	31219
Minus	15	1.31	1630	Plus	26	26.7	33209
Minus	14	1.43	1779	Plus	27	28.3	35200
Minus	13	1.57	1953	Plus	28	30	37312
Minus	12	1.72	2140	Plus	29	31.8	39551
Minus	11	1.8	2338	Plus	30	33.6	41791
Minus	10	2.06	2562	Plus	35	44.6	55472
Minus	9	2.25	2798	Plus	40	58.5	71761
Minus	8	2.45	3047	Plus	45	76	94527
Minus	7	2.68	3333	Plus	50	97.8	120398
Minus	6	2.92	3632	Plus	55	125	155472
Minus	5	3.18	3955	Plus	60	158	196517
Minus	4	3.46	4303	Plus	70	247	307212
Minus	3	3.77	4690	Plus	80	376	467662
Minus	2	4.1	5100	Plus	90	556	691542
Minus	1	4.46	5547	Plus	100		